Exhibit 14.06

United States' Motion to Enter Consent Decree, United States v. Alden Leeds, Inc. et al., Civil Action No. 22-7326 (D.N.J.)

EXHIBIT A-26

Appendix A to OxyChem's Comments in Opposition to Proposed Consent Decree, *United States v. Alden Leeds, Inc., et al.*, Civil Action No. 2:22-cv-07326 (D.N.J.)

FILE #: <u>07 - 14 - 43</u>

NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION SOLID AND HAZARDOUS WASTE ENFORCEMENT

BUREAU: M3

GENERATOR INSPECTION REPORT

FACILITY INFORMATION

FACILITY NAME: Bound More & Co.
EPA ID NUMBER: NTD002456242 CASE NUMBER:
STREET ADDRESS: 134 Lister Avenue
MUNICIPALITY: Newark COUNTY: Fisc.
MAILING ADDRESS: 134 Lister Avenue, Newark, N.J. 07105
TELEPHONE # 201-344-1200 FAX # 201-344-2716
BLOCK :LOT :
FACILITY PERSONNEL: Charles J. Ilsky, JR, Regulatory A FFAirs (name & title) Chemist
Gleva M. Cooper, Plant Operations Manager
INSPECTION DATE: 11-18-96; 11-22-96
INSPECTOR'S NAME & TITLE: Robert A. Aquew, Environmental Specialist
OTHER STATE/EPA PERSONNEL:
REPORT PREPARED BY NROLL A A
REVIEWED BY: A Robert A. Aguew Date of Review: 12-10-96

DEFO DRAFT 10/31/96

888000002

INSPECTION DATE(S): 11-19-74 11-22-76 TIME IN: 1300 0945 TIME OUT: 1430 1420
PHOTOS TAKEN: YES () NO () QUANTITY () ATTACH PHOTO LOG
SAMPLES TAKEN: YES () NO () HOW MANY () ATTACH SAMPLE LOG
SITE BACKGROUND INFORMATION
EMPLOYEES: 10 SHIFTS/WEEK: 13/week
DATE OPERATIONS BEGUN: 1927 SIC CODE: 2851
ACRES: 17 # OF BUILDINGS/SQFT: App. 32,000 Packychian Bid.
PRODUCTS PRODUCED: Batch Parduction of Paints
PREVIOUS OPERATIONS AT SITE: Listers Agricultural Chemicals
NON-HW. TANKS ON SITE: See s.ie dingnam" (provide a list of tanks, location, and capacities)
AIR PERMITS: Air inspection in Oct. 96 AR-0506.7
NJPDES PERMITS: SWG A. OCC. 789
UIC PERMIT: POTABLE WATER ID. NUMBER:
WELL DIVERSION PERMIT(>100,000 gal/day):
WELLS ON SITE: None
PERMITS OTHER: (MUA) 352 ISRA CASE NUMBER:
BUST REGISTRATION #: N/A
COPY OF LAST YEARS RIGHT TO KNOW SURVEY ON SITE?
COPY OF LAST YEARS FORM "R" SURVEY ON SITE? ANNA! Report
DOES THE FACILITY HAVE A POLLUTION PREVENTION PLAN?
WATER SUPPLY-PUBLIC: NEWARK WELL:
SOLID WASTE-POTW: New ARK SEPTIC:
SOLID WASTE-POTW: New ARK SEPTIC: FLOOR DRAINS: N-nc DISCHARGE TO:
FEO

DEFO DRAFT 10/31/96 PAGE 3

INSPECTION & GENERAL FACILITY DESCRIPTION & OPERATIONS

On 11-19-96 and 11-22-96 a RCRA generator inspection was conducted for Benjamin Moore & Co. located at 134 Lister Avenue in Newark N.J. This inspector spoke with Charles J. Ilsley, Jr., regulatory Affairs Chemist and Glenn M. Cooper, Plant Operations Manager. Benjamin Moore & Co. began operations at the Newark facility in 1927. The facility specializes in batch production of water based and oil based paints. Currently, over eighty five percent of the paint manufactured at the facility is water based.

A site tour was conducted with both facility representatives. The facility property is approximately 17 acres in size. The facility's production building has three stories and has approximately 96,000 square feet of floor space. Production begins on the third floor. Water is mixed with pigment and latex resins. The mixture is then dropped to the second floor for thin down processing. Surfactants and defoamers are added to the process. Depending on the product line. Titanium dioxide slurry may be added to the batch. Oil based paints are blended with mineral spirits in the mixing process. Titanium dioxide is only used in the water based process. After blending the paint is fed from the blending tanks to holding tanks on the second floor. The facility has 61 batch blending tanks and several smaller vats for blending special order paints. The filling lines are located on the first floor. There are three one gallon, one two gallon and one one quart, filling lines.

The facility uses a distillation unit to recover mineral spirits used in the tank and vat cleaning processes. Spent/byproduct mineral spirits is stored in totes until it can be distilled. Additionally, there are two parts washers in the QC lab that use odorless mineral spirits. All spent and byproduct mineral spirits are recovered and reused in product manufacturing. Product retain samples are also reused if possible.

The facility has several above ground storage tanks for paint additives such as, vinyl acetate, xyzylol, titanium dioxide and butyl acetate. There are no hazardous waste storage tanks on site.

There are several storage areas for raw materials, product paints and new empty paint containers. Product loading areas include building # 8 and building # 4, tank trailer loading area. Titanium dioxide slurry is delivered to the facility by rail. (Facility diagram is attached).

The facility currently generates two hazardous waste streams. Waste oil/mineral spirit based paints are classified as D001 waste. Caustic solution (sodium hydroxide) also used for process tank cleaning is classified as D002 waste. Waste latex paint related materials are classified as X900 waste.

The following waste was found in the facilities waste storage area.

- 35-55 gallon drums of latex paint waste (X900).
- 4- 55 gallon drums of oil/mineral spirit based paint waste (D001).

All hazardous waste drums were labeled and displayed accumulation start dates. Currently, all hazardous wastes are shipped to North East Chemical Corp. in Cleveland, Ohio. Non hazardous latex waste is shipped to the East Liverpool landfill in Warren, Ohio. (Copy of shipping paper is attached).

55 manifests and associated LDR notifications were reviewed during the inspection. No discrepancies were noted. (Copy of manifest is attached).

Contingency plan, training and preparedness and prevention requirements were reviewed. No discrepancies were noted.

The facility was also inspected for multi media requirements. The facility has air permits for storage tanks and process area vents. (APC Plant ID # 05067). A listing of air permits is attached. The facility has a storm water permit. (SWG A-006789). They also have a sewer connection permit with the City of Newark. (Permit # 352). The facility reports that there are no underground storage tanks on site.

DFWE 29 REV 02/22/93


SUMMARY OF FINDINGS

Benjamin Moore & Co. was previously inspected on 9-7-94 and 4-13-92. No violations were cited on the last inspection.

SUMMARY OF VIOLATIONS

" No violations were noted".

DFWE 29 REV 02/22/93



Case 2:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 8 of 22 PageID: 9322

HAZARDOUS WASTE INVENTORY

LOCATION	WASTE CODES	DESCRIPTION	QUANTITY PRESENT
Drum HORAYE AKCA	Door	Minceal Spirits	4-55 gal. deuns
· · · ·	IDIZ	Waste latex	35.35 gal deuns.
	,		

Case 2:22-cv-07326-MCA-LDW Document 29156_{RE} Diled 01/31/24 Page 9 of 22 PageID: 9323

Manifests reviewed from 11-18-96 through 11-18-96	
Number of manifests in compliance:	55
Number of manifests <u>NOT</u> in compliance:	0
Total number of manifests reviewed:	5
According to the manifests, does the facility import or export any waste? YES	_NO
(if yes, complete the import/export section of this report)	
List manifest document numbers of those manifests not in compli- deficiency.	ance and note each
Attach copies of manifests which have deficiencies.	
Manifest# DATE N.J.A.C.7:26G- Comments	
	· · · · · · · · · · · · · · · · · · ·
•	
	
	
	·
	·
	

CHECK THE SECTIONS AND ACTIVITIES OF THIS REPORT WHICH ARE APPLICABLE TO THE FACILITY AND COMPLETE THOSE SECTIONS FOR THIS INSPECTION.

SECTIONS NOT APPLICABLE ARE NOT INCLUDED IN THE REPORT.

GENERATOR WASTE MANAGEMENT PRACTICES

#	SECTION	PAGE
1.	MULTI MEDIA CHECKLIST	7/
2.	WASTE DETERMINATION	8/
3.	GENERATOR STATUS	.9
4.	SATELLITE STORAGE AREAS	10.
5.	GENERATOR STORAGE AREAS	11.
6.	GENERATOR ABOVE GROUND TANKS STORAGE AREAS	12.
7.	WASTE OIL USAGE	13. 🗸
8.	WASTE MANAGEMENT PRACTICES	14. 🗸
9.	GENERATOR MANIFESTS	15.
10.	HAZARDOUS WASTE EXPORTATION	17
11.	CONTINGENCY PLAN & EMERGENCY PROCEDURES	19
12.	PERSONNEL TRAINING	21.
13.	PREPAREDNESS & PREVENTION	23.
14.	WASTE WATER TREATMENT PLANT QUALIFICATION	24.

SECTION 1

MULTI MEDIA INSPECTION CHECKLIST

THE FOLLOWING CHECKED AREAS OF CONCERN WERE IDENTIFIED. EACH APPROPRIATE SECTION OF THE MULTIMEDIA CHECKLIST WAS COMPLETED AND IS INCLUDED IN THE REPORT.

井	<u>SECTION</u>	
1.	AIR POLLUTION CONTROL	
2.	WATER POLLUTION CONTROL	
3.	UNDERGROUND STORAGE TANKS	
4.	TOXIC SUBSTANCES CONTROL ACT (TSCA)	
5.	EMERGENCY PLANNING AND COMMUNITY RIGHT TO KNOW	· · · · · · · · · · · · · · · · · · ·
6.	SPILL PREVENTION (DISCHARGE PREVENTION), CONTROL, AND COUNTERMEASURES (SPCC & DPCC) PLANS	····
7.	WETLANDS	
8.	ISRA (FORMERLY ECRA)	
9.	SPILL ACT	···········
10.	OSHA PROGRAMS & TRAINING REQUIREMENTS	
	No AneA4 of concern were not	ed "

Case 2:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 12 of 22 PageID: 9326

SECTION 2

	WASTE DETERMINATION				
		YES	NO		
<u>DOES</u> the facility g	enerate "solid wast e ".				
DOES the facility g	enerate a "hazardous waste".				
IS THE FACILITY COR	RECTLY CLASSIFYING ITS WASTES?				
IF NO, CHECK THE IT	EMS OF NON COMPLIANCE.				
262.11	Generator <u>failed</u> to determine if its "solid wis hazardous?	aste".		+ t	
262.40	Generator <u>failed</u> to keep records of test result analysis, or other determination for 3 years.				
•	COMMENTS				

Case 2:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 13 of 22 PageID: 9327

SECTION 3.

GENERATOR STATUS

	YES NO	
Does the generator generate >100 kg of hazardous waste		
(1 kg acutely) in any calender month or accumulate more		
than 1000 kg of hazardous waste on site?	·	
IF YES,		
OCO 10/1) Who Company That The chick on The Twee Company		
262.12(a) The Generator FAILED to obtain an EPA ID number.		
TO WITE COMPANION TO A CECOC		
IF THE GENERATOR IS A CESQG,		:
Does the generator wish to deactivate his EPA ID number?		
Does the generator wish to deactivate his Era in humber:		
		à
COMMENTS		
		
		÷
•	•	
		-
	•	

SECTION 4

SATELLITE ACCUMULATION AREAS

	YES	NO
IS THE FACILITY I REGULATIONS?	N COMPLIANCE WITH THE SATELLITE ACCUMULATION	
REGULATIONS:		
IF NO, CHECK THE	ITEMS OF NONCOMPLIANCE.	
N.J.A.C.		
7:26G-6.1(a)-		
262.34 (c)	(1) Quantity of waste <u>EXCEEDS</u> 55 gal. or 1 qt. of acutely hazardous waste.	· ·
262.34 (c)	(1)(i) Containers <u>NOT</u> in good condition (Failed to meet the standards of 265.171 Container requirements).	
	Container leaking.	
265.172	Container made of incompatible material.	
265.17 3(a)	Container not kept securely closed.	
262.34 (c)	(1) Accumulation area is:	
	NOT at or near a point of generation.	
	NOT under the control of the operator.	
262.34 (c)	(1)(ii) Containers <u>NOT</u> marked "Hazardous waste" or With other words which identify the waste.	
262.34 (c)	(2) Containers <u>NOT</u> marked with date when filled.	
262.34 (c)	(1) Containers \underline{NOT} moved from satellite area within three days.	
	COMMENTS	

Case 2:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 15 of 22 PageID: 9329

SECTION 5

LARGE QUANTITY GENERATOR CONTAINER ACCUMULATION AREAS IS THE FACILITY IN COMPLIANCE WITH THE GENERATOR STORAGE REGULATIONS? IF NO, CHECK THE ITEMS OF NONCOMPLIANCE. N.J.A.C. 7:26G-6.1(a) NO manifest number on containers ready for disposal. 262.31 263.30 Containers FAILED to meet DOT regulations. (49 CFR 171,179) specs for packaging/labeling. Waste ACCUMULATED OVER 90 DAYS FOR L. Q. G. 262.34 (a) Containers NOT marked: With accumulation start date 262.34 (b) (3) OR THE WORDS "Hazardous Waste". 262.34(a) (1) (i) Containers NOT of adequate construction. 262.34(a) (1) (i) Closures NOT of sufficient strength. 262.34(a) (1) (i) Containers NOT in good condition/owner FAILED 262.34(a) to transfer. (1) (i) Containers NOT compatible with waste. 262.34(a) 262.34(a) (1) (i) Containers NOT kept closed. (1) (i) Containers NOT managed properly to prevent 262.34(a) rupture/leak. 262.34(a) (1) (i) Incompatible hazardous wastes NOT segregated. (2) ID Labels NOT visible. **262.34**(a) 262.34(a) (2) Accumulation area NOT inspected weekly. 262.34(a) (2) Containers of ignitable and reactive wastes. NOT located at least 50 feet from the facility's

(4) Access to communication or alarm system is NOT

property line.

maintained.

INADEQUATE aisle space.

262.34(a)

262.34(4)

Case 2:22-cv-07326-MCA-LDW Document 291 $_{50}$ Filed 01/31/24 Page 16 of 22 PageID: 9330

GENERATOR MANIFESTS

	G - 262) (SUBPART B)	
IF NO, CHECK T	HE ITEMS OF NONCOMPLIANCE	
262.20(a)	Generator FAILED to prepare a manifest before a generator transports, or offers for transportation, hazardous waste for offsite treatment, storage, or disposal, according to the instructions included on the back of the manifest form.	
	K of the manifest shall be completed even if the instructions of an out-of-st not address the shaded portions.	ate
262.20(a)	Generator FAILED to include the following information on a manifest:	
	Generator's name, mailing address, site address, and phone number	
	Generator's EPA I.D. number	
	Transporter(s) name, phone number, or New Jersey registration number	
	Transporter(s) EPA I.D. number	
•	Name, address and phone number of designated TSDF facility	
	TSDF's EPA I.D. number	
	Proper USDOT (49CFR Parts 171-177) description of waste	
	Special handling instructions, including DOT descriptions for NOS material & 2 major constituents, a 24 hour emergency number as per 49 CFR 172.201(d), or decal number.	
	Generator FAILED to complete Items A-K (shaded portions) of the manife	st?
N.J.A.C.7:26G-6	Generator FAILED to utilize the proper waste code(s) that accurately (formerly 7.4(a)4x) describe the shipment of hazardous waste, determined according to the waste "Hierarchy"	
262.20(b)	Generator FAILED to designate on the manifest one facility that is permitted to handle waste described on the manifest	
262.20(c)	Generator FAILED to designate one alternate facility in the event an emergency prevents the hazardous waste shipment from being delivered to primary designated facility.	
26 2.4 0(a)	Generator FAILED to retain copy of each manifest, in accordance with 262.23(a) for three (3) years, or until he receives a signed copy from the designated facility which received the waste. This signed copy must be retained onsite for at least three (3) years from the date the waste was accepted by the initial transporter.	
262.23(a)(1)	Generator FAILED to sign the manifest certification by hand.	
262. 23 (a)(2)	Generator FAILED to obtain the handwritten signature of the initial transporter and date acceptance on the manifest.	
262.23(a)(3)	Generator FAILED to retain one copy of the manifest signed by the generator and the initial transporter, in accordance with 262.40.	
262.2 3 (b)	Generator FAILED to give transporter the remaining copies of the manifest.	

YES

29:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 17 of 22 PageID: 9331 GENERATOR MANIFESTS (cont.) 262.23(c) Generator FAILED to send three (3) copies of the manifest dated and signed in accordance with this section to the owner or operator of the designated facility or the last water (bulk shipment) transporter to handle the waste in the United States if exported by water. Applicable for shipments of hazardous waste within the United States solely by water (bulk shipments only). (Copies of the manifest are NOT required for each transporter). Generator FAILED to send at least three copies of the manifest dated and 262.23 (d) signed in accordance with this section, in regards to rail shipments of hazardous waste within the United States which originate at the site of generation, to: 262.23 (d) 1 The next non-rail transporter (if any); or, 262.23 (d) 2 The designated facility if transported solely by rail; or 262,23 (d) 3 The last rail transporter to handle the waste in the United States if the waste is exported. 262.23(e) Generator FAILED to assure that the designated facility agrees to sign and return the manifest to the generator, and that any out-of-state transporter signs and forwards the manifest to the designated facility, in regards to shipments of hazardous waste to a designated facility in an authorized State which has not yet obtained authorization to regulate that particular waste as hazardous. The requirements of this subpart (Subpart B-The Manifest) do not apply to

- The requirements of this subpart (Subpart B-The Manifest) do not apply to hazardous waste produced by Generator's of greater than 100 kg, but less than 1,000 kg in a calendar month, if waste is reclaimed offsite. However, it shall still be considered a violation if Generator fails to meet any of the following requirements:
- 262.20(e)(1) Generator FAILED to have a contractual agreement(s) while having the hazardous waste reclaimed offsite (indicate in narrative section who Generator has contractual agreement with).
- 262.20(e)(1)(i) Generator FAILED to indicate the type of waste, and the frequency of shipments in their contractual agreement(s).
- 262.20(e)(1)(ii) Generator FAILED to utilize a vehicle owned, and operated by the reclaimer of the hazardous waste, used to transport the waste to the recycling <u>facility</u> and to deliver regenerated material back to the generator.
- 262.20(e)2 Generator FAILED to maintain a copy of their reclamation agreement onsite for a period of three (3) years after the termination or expiration of the agreement.

Case 2:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 18 of 22 PageID: 9332 GENERATOR MANIFESTS (cont.)

MANIFEST RECORD KEEPING & REPORTING

IS THE FACILIT (N.J.A.C. 7:26	Y IN COMPLIANCE WITH THE GENERATOR RECORD-KEEPING & REPORTING REGULATIONS?
IF NO, CHECK T	HE ITEMS OF NONCOMPLIANCE
262.40 RECOR	D KEEPING
for faci for	erator FAILED to retain copy of each manifest, in accordance with 262.23(a) three (3) years, or until he receives a signed copy from the designated lity which received the waste. This signed copy must be retained onsite at least three (3) years from the date the waste was accepted by the initial asporter.
	erator FAILED to keep a copy of each Biennial Report and Exception Report a period of at least three years from the due date of the report.
automatically o	62.40(d), the periods of retention referred to in this section are extended during the course of any unresolved enforcement action regarding the regulated requested by the Administrator.
262.41 BIENN	IAL REPORT.
262.41 (a)	Generator FAILED to prepare and submit a single copy to the Regional Administrator by March 1 of each even numbered year, when the facility shipped a hazardous waste offsite to a treatment, storage, or disposal facility within the United States. The Biennial Report must also cover Generator activities during the previous year.
262.41(a)	Generator FAILED to include the following information on a Biennial Report:
262.41(a)1	Generator's USEPA I.D. number, name, and address
262.41 (a) 2	Calendar year covered by the Biennial Report
262.41 (a) 3	USEPA ID number, name and address for each off-site TSDF used by Generator during the year.
262. 4 1(a)4	USEPA I.D. number and name of each transporter used during the reporting year for shipments to TSDF'S.
262.41(a)5	The description, EPA hazardous waste number (from 40 CFR part 261, (subpart C or D), DOT hazardous class, and quantity of each hazardous waste shipped offsite for shipments to TSDF's (Information must be listed by USEPA I.D. number of each offsite TSDF to which waste was shipped).
2 62.41(a) 6	Description of the efforts undertaken during the year to reduce the volume and toxicity of waste generated.
262. 41 (a)7	Description of the changes in volume and toxicity of waste actually achieved during the year in comparison to the previous years.
262.41(a)8	The certification is signed by the Generator or authorized representative
262.41(b)	Generator, who treats, stores, or disposes of hazardous waste onsite, FAILED To submit a Biennial Report covering those wastes in accordance with the provisions of 40 CFR parts 270, 264, 265, and 266.

YES

NO

262.42 EXCEP	TION REPORTING	
262. 42(a) 1	Generator, of greater than 1000 kg of hazardous waste in a calender mont who has not received a copy of the manifest with the handwritten signature of the owner or operator of the designated facility within 35 days of the date the waste was accepted by the initial transporter, FAILED to contact the transporter and/or the owner or operator of the designated facility determine the status of the hazardous waste.	ire ie ot
262.42(a)2	Generator, of greater than 1000 kg of hazardous waste in a calender mont FAILED to submit an Exception report to the Department when the facility has not received a copy of the manifest with the handwritten signature of the owner or operator of the designated facility within 45 days of the designated waste was accepted by the initial transporter.	, of
	The Generators Exception Report failed to include:	
262.42(a)(2)i	A legible copy of the manifest for which the generator does not have confirmation of delivery.	
262.42(a)(2)ii	A cover letter, signed by the generator or his authorized representative explaining the efforts taken to locate the hazardous waste and the resul of those efforts.	
262; 42 (b)	Generator, of greater than 100 kg but less than 1000 kg of hazardous was in a calendar month, who does not receive a copy of the manifest with th handwritten signature of the owner or operator of the designated facility within 60 days of the date waste was accepted by the initial transporter FAILED to submit a legible copy of the manifest, with same indication to generator has not received confirmation of delivery to the Department.	e Y
NOTE: The submi	ssion to DEP need only be a handwritten or typed note on the manifest itse sheet of paper, stating that the return copy was not received.	elf, or
262.44 SPECIAL 1	REQUIREMENTS FOR GENERATOR'S OF BETWEEN 100 AND 1000 KG/MONTH OF HAZARDOUS	WASTE
	or of greater than 100 kg but less than 1000 kg of hazardous waste in a cat only to the following requirements under RECORD KEEPING & REPORTING:	lendar
(a) Section	262.40(a) Retaining manifest copies onsite for 3 years	
•	262.40(c) Retaining of test results/analysis for 3 years	
	262.40(d) Retention time extension's	
(b) Section	262.42(b) Exception reporting requirements	
(c) Section	262.43 Additional reporting	
	<u>COMMENTS</u>	
·		
	•	

<u> </u>		

Case 2:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 19 of 22 PageID: 9333

GENERATOR MANIFESTS (cont.)

CONTINGENCY PLAN AND EMERGENCY PROCEDURES

IS THE FAC	CILITY IN COMPLIANCE WITH THE CONTINGENCY PLAN & EMERGENCY PROCEDURES NS?	
IF NO, CHE	ECK THE ITEMS OF NONCOMPLIANCE.	
265.51(a)	NO written contingency plan.	
265.51 (b)	Generator FAILED to implement the plan in an emergency.	
265.52(a)	Plan FAILED to describe the response actions facility personnel and local authorities shall take.	
265.52(b)	Generator has a DPCC or SPCC Plan and FAILED to amend that plan to incorporate hazardous waste management.	
265.52(c)	Plan FAILS to describe arrangements agreed to by local authorities.	
2 6 5. 52 (d)	Plan FAILS to list names, addresses, and phone numbers (office and home) of emergency coordinators.	
265.52(e)	Plan FAILS to include a list, location, AND CAPABILITIES of all emergency equipment.	
265.52(f)	Plan FAILS to describe evacuation procedures, evacuation signal(s) AND routes.	
Generator	FAILED to:	
265.53 (a)	1. Keep a copy of the plan at the facility.	
265.53 (b)	2. Submit the contingency plan to local authorities.	
265.54	Generator FAILED to revise the contingency plan when:	
	(a). Applicable regulations are revised.	
	(b). The plan fails.	
•	(c). The facility changes.	
	(d). The Emergency Coordinator changes.	
	(e). The emergency equipment changes.	
265.55	Emergency coordinator NOT available.	
N.J.S.A. 58	3:10-23.11(c) There is a discharge of a hazardous substance.	
N.J.S.A. 58	3:10-23.11(e) Facility FAILED to report the discharge.	
	COMMENTS:	

Case 2:22-cv-07326-MCA-LDW Document $\frac{291}{5ECTTON} = \frac{6}{13}$ Filed 01/31/24 Page 21 of 22 PageID: 9335

•	PERSONNEL TRAINING	<u>G</u>		
IS THE FACILITY IN	N COMPLIANCE WITH THE PERSONNEL TRAINING	G REGULATIONS?	YES	NC
THE TRAINING PROGE	RAM UTILIZES CLASSROOM TRAINING?			
ON THE JOB TRAININ	NG?		1	
BOTH CLASSROOM &N	THE JOB TRAINING?		1	
IF NO, CHECK THE I	TEMS OF NONCOMPLIANCE.			
	ning program NOT directed by a person transcript transcript to the procedures and,	rained in hazardous waste		
	lesigned to ensure that facility personn	nel are able to respond effect	ively	-
26 4.16(a)(3) Prog r equipme	am FAILS to include the following emergent:	gency response procedures and		
264.16(a)(3)(i)	Procedures for using facility emergence	cy and monitoring equipment.		
264.16(a)(3)(ii)	Key parameters for automatic waste fee	ed cut-off systems.		
264.16(a)(3)(iii)	Procedures for utilizing communication	ns or alarm systems.		
264.16(a)(3)(iv)	Response procedures for fires & explos	sions.		
264.16(a)(3)(v)	Ground water contamination response pr	rocedures.		
264.16(a)(3)(vi)	Shutdown procedures.			
	el have NOT successfully completed trair employment or assignment to a new pos		da te	
264.16(b) Personn	el work unsupervised before training pr	ogram is completed.		
264.16(c) Personn	el do NOT take part in an annual review	of training.		
264.16(d) NO writ	ten documentation of the following:			
264.16(d)(1)	Job title for each position and the na	ame of the employee filling ea	.ch job	•
26 4.16(d)(2)	A written job description.			
2 64.16 (d)(3)	Description of the training given to p	personnel.		
264.16(d)(4)	Documentation of actual training.		÷	
264. 16(e) Trainin	g records NOT kept.			
	COMMENTS			

Case 2:22-cv-07326-MCA-LDW Document 291-6 Filed 01/31/24 Page 22 of 22 PageID: 9336

PREPAREDNESS AND PREVENTION

IS THE FAC	CILITY IN COMPLIANCE WITH THE PREPAREDNESS & PREVENTION REGULATIONS?	YES	NO
IF NO, CHE	ECK THE ITEMS OF NONCOMPLIANCE.		
265.32	Facility FAILS to have:		
265.32(a)	Communications or alarm system.		
265.32(b)	A telephone or device to summon emergency assistance.		
265.32(c)	Portable emergency equipment.		
265.32(d)	Adequate Water supply.		
265.33	Generator FAILED to test and maintain emergency equipment.		·
Generator	FAILED to:		
265.37(a)(1) Familiarize Police, fire departments, and emergency response teams with the layout of the facility, & hazardous waste handled.	е	
265.37(a)(2) Have an agreement designating primary emergency authority to a specific poland fire department where more than one Police and fire department are invol		
265.37(a)(3) Make agreements with emergency response contractors, and equipment supplies	٤.	
265. 37(a)(4) Make arrangements to familiarize local hospitals with the properties of haz waste handled at the facility and the types of injuries result from fires, explosions, or discharges at the facility.	zardou	s ·
265. 37 (b)	Document when authorities identified in (f)1 through 5 above declined to entinto such arrangements.	ter	
	COMMENTS		
•	• .		
·			
			·